BoRit Asbestos NPL Site Weekly Summary October 7, 2013 – October 11, 2013

## REMOVAL OPERATIONS UPDATE

### Work completed this week

- 1. Continued removing tree stumps along the Pile side of the Reservoir berm.
- 2. Continued loading the stumps in the roll-offs for off-site disposal.
- 3. Continued receiving clean fill.
- 4. Continued building the platform, at corner of Reservoir closest the back of the Pile, for the pump and treat system.
- 5. Precipitation: approximately 2 1/4 inches.

## Work scheduled for next week

- 1. Complete removing tree stumps along the Pile side of the Reservoir berm.
- 2. Continue loading the stumps in the roll-offs for off-site disposal.
- 3. Continue to receiving clean fill.
- 4. Complete building the platform, at corner of Reservoir closest the back of the Pile, for the pump and treat system.
- 5. Start spreading the waste under the black geotextile fabric (at the Park) and covering with clean material (final elevations).

### **REMEDIAL OPERATIONS UPDATE**

1. Nothing to report.

# **COMMUNITY INVOLVEMENT OPERATIONS UPDATE**

1. Nothing to report.